PAGE 1

Smith-Hill and Bedell, P.C.

PATENT AND TRADEMARK LAWYERS

12670 NW Barnes Rd., Suite 104 Portland, Oregon 97229 Telephone: (503) 574-3100

Facsimile: (503) 574-3197

RECEIVED CENTRAL FAX CENTER

FEB 0 8 2005

John Smith-Hill

Daniel J. Bedell

## FACSIMILE COVER SHEET

Ian N. Moore To:

Art Unit 2661

Firm:

US PATENT AND

TRADEMARK OFFICE

Fax: 1-703-872-9306

Your ref: 09/847,079

From: Daniel J. Bedell

Date: February 8, 2005

Our ref: ZETT 2151

Pages: Cover + 13

BEST AVAILABLE COPY

Art Unit: 2661

Examiner:

Ian N. Moore

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of

Toan D. TRAN et al

Application No: 09/847,079

Filed: May 1, 2001

For: BACK PRESSURE CONTROL SYSTEM FOR

NETWORK SWITCH PORT

REPLY TO THE OFFICE ACTION MAILED 10/18/2004

COMMISSIONER FOR PATENTS
P.O. Box 1450
Alexandria, Virginia 22313-1450

Sir:

Further examination and consideration of this application are requested in view of the following Amendments and Remarks.

## This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

□ BLACK BORDERS
□ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
□ FADED TEXT OR DRAWING
□ BLURRED OR ILLEGIBLE TEXT OR DRAWING
□ SKEWED/SLANTED IMAGES
□ COLOR OR BLACK AND WHITE PHOTOGRAPHS
□ GRAY SCALE DOCUMENTS
□ GRAY SCALE DOCUMENTS
□ LINES OR MARKS ON ORIGINAL DOCUMENT
□ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

## IMAGES ARE BEST AVAILABLE COPY.

☐ OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.